

EAST Search History

Ref #	Hits	Search Query	DBs	Default Plurals Operator		Time Stamp
L3	3992	375/316	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/12/07 14:28
L4	32	"375239"	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR ·	ON	2006/12/07 14:54
L5	515	375/239	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/12/07 15:14
L6	3007	375/295	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/12/07 14:54
L7	2032	375/343	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/12/07 15:22
L8	3817	375/354	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/12/07 15:22
L9	7	demodulat\$3 same squar\$3 near (in adj phase I) same squar\$3 near (quadrature Q)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/12/07 15:38
L10	156	squar\$3 near (in adj phase I) and squar\$3 near (quadrature Q) not L9	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/12/07 15:38

EAST Search History

L11	129	squar\$3 near (in adj phase I) same squar\$3 near (quadrature Q)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/12/07 15:38
L12	34	squar\$3 near (in adj phase I) and squar\$3 near (quadrature Q) not L9 not L11	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/12/07 15:44
L13	34	squar\$3 near (in adj phase I) and squar\$3 near (quadrature Q) not L9 not L11	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/12/07 15:53
S1	7	demodulat\$3 same squar\$3 near (in adj phase I) same squar\$3 near (quadrature Q)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/12/06 21:13
S2	129	squar\$3 near (in adj phase I) same squar\$3 near (quadrature Q)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/12/06 21:19
S3	122	squar\$3 near (in adj phase I) same squar\$3 near (quadrature Q) not S1	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/12/07 15:38



Welcome United States Patent and Trademark Office

Search Session History

Edit an existing query or compose a new query in the

Search Query Display.

BROWSE

SEARCH

IEEE XPLORE GUIDE -

SUPPORT

Thu, 7 Dec 2006, 3:20:18 PM EST

Search Query Display



•	Add	а	query	to	the	Search	
	Que	rv	Displa	aν			

Select a search number (#)

- Combine search queries using AND, OR, or NOT
- Delete a search

to:

• Run a search

Recen	Results	
<u>#1</u>	(((squaring <or>squared<or>square<and>in phase) <and>quadrature<and>multiplying) <and> (pyr >= 1950 <and> pyr <= 2002)<in>metadata)</in></and></and></and></and></and></or></or>	2563
<u>#2</u>	((squaring <or>squared<or>square<and>in phase) <and>quadrature) <and> (pyr >= 1950 <and> pyr <= 2002)</and></and></and></and></or></or>	9046
<u>#3</u>	((squaring in phase <and>squaring quadrature)) <and> (pyr >= 1950 <and> pyr <= 2002)</and></and></and>	0
<u>#4</u>	((squaring in phase <and>squaring quadrature)) <and> (pyr >= 1950 <and> pyr <= 2002)</and></and></and>	. 0
<u>#5</u>	((in phase squared <or> i squared<and>quadrature squared<or>q squared)) <and> (pyr >= 1950 <and> pyr <= 2002)</and></and></or></and></or>	102



Help Contact Us Privacy & Security IEEE.org

© Copyright 2006 IEEE – All Rights Reserved

indexed by in Inspec*